

Project Name: VANDENBERG AFB IRP: OU 2, Site 20, Landfill 1/Drum Disposal Site 1		
Project Number: 01K78601	Borehole No.: 20-MW-13	Sheet 1 of 2
Borehole Location: 2099493.94 N, 5801890.22 E		Elevation and Datum: 456.30 feet MSL
Drilling Contractor: Tri-County Drilling, Inc.	Date Started: 05/18/98	Date Ended: 05/19/98
Drilling Equipment: CME-75	Total Depth: 54 feet	Groundwater Depth: 45 feet
Drilling Method: Hollow Stem Auger	Sampling Method: Split Spoon	Borehole Diameter: 11 inches
Driller: M. Ferguson	Borehole Abandonment: Completed as 4" monitoring well	
Hammer Information: Manual Hammer: 140-lb and 30-inch drop	Logged By: D. Peeler	Checked By: M. Anderson

Depth (feet)	Lithologic Description	Symbol	USCS	Sample	Sample Number	Blow Counts	Field OVA (ppm)	Remarks
0-7	SILTY SAND, dark yellowish brown (10YR 4/4), slightly moist, loose, with silt (40%) and trace shale gravel.		SM				0	Hand augered to 7 feet Second attempt 5 feet North of first attempt.
5-10	CLAYEY SAND, light brownish gray (2.5Y 6/2), slightly moist, stiff, firm, medium plasticity to very stiff, hard, with moderate cementation.		SC				0	Resembles "caliche".
10-15	SANDY CLAY, very pale brown (10YR 8/2), dry, hard brittle thin lenses alternate with slightly moist, firm, low plasticity, sandier lenses. SANDY CLAY, light olive brown (2.5Y 5/4), slightly moist, stiff, firm, low plasticity, with sand (40%).		CL				0	
15-20	Same as above, olive brown (2.5Y 4/3).		CL				0	
20-25	CLAY, very pale brown (10YR 8/2), dry, hard, weak cementation, with sand-size rock fragments (20%).		CL				0	
25-30	CLAY, grayish brown (2.5Y 5/2), slightly moist, firm, medium plasticity, with sand (10%) and well rounded gravel up to 1/2" (<10%).		CL				0	
30-31	SANDY CLAY, dark greenish gray (10Y 4/1), moist, high plasticity, with sand (20%) and gravel (20%).		CL				0	Organic odor.
31-33	SANDY CLAY, olive brown (2.5Y 4/4), dry, stiff, firm low plasticity, with sand (30%) and		CL					

Project Name: VANDENBERG AFB IRP: OU 2, Site 20, Landfill 1/Drum Disposal Site 1

Project Number: 01K78601

Borehole No.: 20-MW-13

Sheet 2 of 2

Depth (feet)	Lithologic Description	Symbol	USCS	Sample	Sample Number	Blow Counts	Field OVA (ppm)	Remarks
	subangular to subrounded chert gravel (20%). Same as above, medium plasticity.		CL				0	Easier drilling.
	Same as above, high plasticity, less gravel (10%).		CL				0	
35	GRAVELLY CLAY with SAND, olive brown (2.5Y 4/3), moist, soft, high plasticity, with sand (25%) and angular, flat chert up to 3" long or rounded chert gravel (30%).		CL				0	
40	Same as above, less sand (20%), very soft.		CL				0	
45							0	
50	CLAY, wet, very soft, with sand (15%) and gravel up to 1/2" (<10%).		CL				0	
55	CLAYEY GRAVEL, very dense, subangular to well rounded chert gravel up to 1", with clay (20%).		GC					Very hard drilling. Rock not fractured, failed to locate major fracture zone after 2 attempts.
	ROCK, very dark grayish brown (10YR 3/2), laminated, dry, hard with gravel (<5%) and trace sand.		RX					
60	End of boring at 54 feet below ground surface. Groundwater encountered at 45 feet. Boring completed as 4" monitoring well.							
65								
70								